

2024-10-19 12:53:20.410 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration xiaomi_mio_raw which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:20.416 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration mio_yeelink which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:20.421 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration hacs which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:20.426 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration smartthings_sensors which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:20.430 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration xiaomi_miot which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:20.435 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration xiaomi_cloud_map_extractor which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:20.439 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration sonoff which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:20.443 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration

rhvoice which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:20.447 WARNING (SyncWorker_0)
[homeassistant.loader] We found a custom integration home_connect_alt which has not been tested by Home Assistant. This component might cause stability problems, be sure to disable it if you experience issues with Home Assistant

2024-10-19 12:53:23.047 WARNING (Recorder)
[homeassistant.components.recorder.util] The system could not validate that the sqlite3 database at //config/home-assistant_v2.db was shutdown cleanly

2024-10-19 12:53:23.127 WARNING (Recorder)
[homeassistant.components.recorder.util] Ended unfinished session (id=598 from 2024-10-13 09:45:15.831507)

2024-10-19 12:53:37.069 ERROR (SyncWorker_4)
[homeassistant.components.xiaomi_tv.media_player] Could not find Xiaomi TV with specified IP: 192.168.1.34

2024-10-19 12:53:40.677 WARNING (MainThread)
[homeassistant.setup] Setup of stream is taking over 10 seconds.

2024-10-19 12:54:08.677 ERROR (MainThread)
[hass_nabucasa.auth] Unable to refresh token: Refresh Token has been revoked

2024-10-19 12:54:34.616 WARNING (MainThread)
[homeassistant.bootstrap] Waiting on integrations to complete setup: {'xiaomi_miot', '8eebc77b1774452f0b31786c920b5658'}: 4537.70109887}

2024-10-19 12:54:35.766 WARNING (MainThread)
[homeassistant.components.light]
light.yeelink_color3_ea06_light (<class 'custom_components.xiaomi_miot.light.MiotLightEntity'>) does not report a color mode, this will stop working in Home Assistant Core 2025.3, please create a bug report at <https://github.com/al-one/hass-xiaomi-miot/issues>

2024-10-19 12:54:35.781 WARNING (MainThread)
[homeassistant.components.light]
light.yeelink_color3_a687_light (<class 'custom_components.xiaomi_miot.light.MiotLightEntity'

```
>) does not report a color mode, this will stop
working in Home Assistant Core 2025.3, please create
a bug report at https://github.com/al-one/hass-xiaomi-miot/issues
2024-10-19 12:54:35.794 WARNING (MainThread)
[homeassistant.components.light]
light.yeelink_color4_8cba_light (<class
'custom_components.xiaomi_miot.light.MiotLightEntity'
>) does not report a color mode, this will stop
working in Home Assistant Core 2025.3, please create
a bug report at https://github.com/al-one/hass-xiaomi-miot/issues
2024-10-19 12:54:35.809 WARNING (MainThread)
[homeassistant.components.light]
light.yeelink_color3_a343_light (<class
'custom_components.xiaomi_miot.light.MiotLightEntity'
>) does not report a color mode, this will stop
working in Home Assistant Core 2025.3, please create
a bug report at https://github.com/al-one/hass-xiaomi-miot/issues
2024-10-19 12:54:35.822 WARNING (MainThread)
[homeassistant.components.light]
light.yeelink_color5_6842_light (<class
'custom_components.xiaomi_miot.light.MiotLightEntity'
>) does not report a color mode, this will stop
working in Home Assistant Core 2025.3, please create
a bug report at https://github.com/al-one/hass-xiaomi-miot/issues
2024-10-19 12:54:55.371 ERROR (MainThread)
[pyhap.hap_handler] HASS Bridge: Client
('192.168.1.29', 49420) with uuid 136c936e-232c-46ca-
a9a4-a8d5eb234866 attempted pair verify without being
paired first
(public_key=cbbeaefc9bd95533acd5dd5d7745ac7d19415c897
675426c07cdaa1d77036a23, paired
clients={UUID('5ecc88a9-8030-4850-
b854-4abb6bceb870'):
'e551732349b91eb47d5b75f2c7014b0bdf20e3be6a78067b548a
91ed3ea77106', UUID('49bea0a9-9454-4975-
a130-787ab11a7b91'):
'c7d987491fff297f1dd1e3cba3f6cf60b19053c45bb9abe96425c
9234a2acdc06', UUID('6d2101a4-
b0af-47da-858f-4cbe8b05ba2d'):
'4476eb50570044c943a202c6af011e403b4f3b4f10af18029855
```

