

Incident Report for 8/20/2022 Environmental Incident (Incident ID: 1756)

Initial Update Close Out

Incident Details		Reporting Party Details		
<p>Description: On the 4th St. NW Center Pipeline Project (47.47463, -102.68307), four small inadvertent returns occurred on 8/20/2022 on the Bore 6 HDD. One appeared to have occurred at Sta. 50+10, 50+13, 50+17, and 50+25 where a total of approx. 3 gallons of bore mud using NSF-60 bentonite surfaced. All IR spots were contained with silt fence, are being monitored, and a hydro-vac truck used to suck up any surface fluid. These spots will be monitored till the HDD is complete and then finish cleanup and restoration. 8/26/2022: HDD bore has been completed. Final IR cleanup, seeding, and mulching has occurred.</p>		<p>Incident Date and Time: 8/20/2022 06:00 PM</p>		
<p>Incident Type: Environmental Incident Incident Subtype : Other: Inadvertent Return</p> <p>Source Type: Other: HDD Source Subtype:</p> <p>Incident Status: Active Released Into Medium : Vegetation, Soil</p>		<p>Reporting Party Name: George Hilvers Reporting Party Company: MPLX</p> <p>Reporting Party Phone: Reporting Party Email:</p> <p>Reported Date and Time: 8/22/2022 8:30 AM</p>		
Site Details		Incident Location		
<p>Is Spill Continuous: No Is Spill Contained: Yes</p> <p>Discovered/Start Date and Time: 8/20/2022 06:00 PM End Date and Time: 8/20/2022 07:00 PM</p> <p>Reported to NRC: No</p> <p>Well Name : NDIC File Number :</p> <p>Oil/Gas Operator : Oil/Gas Field Name :</p> <p>Extent of Spill/Release: Confined to Property of Origin</p> <p>Extent Details:</p>		<p>Address:</p> <p>Location Description:</p> <p>Latitude: 47.4746299999992 Longitude: -102.683069999998</p> <p>Section: 8 Township: 146 N</p> <p>Range: 94 W Quarter: SE¼</p> <p>Quarter: SW¼ Source Water Protection Area:</p> <p>County/Tribe: Dunn County Fire District: WEST DUNN FIRE</p>		
Incident Contacts				
Responsible Authority Contact		Responsible Authority Compliance Contact		Property Owner Contact
<p>Name: Paige Travis</p> <p>Title: Project Construction Specialist</p> <p>Company Name: MPLX</p>		<p>Name: George Hilvers</p> <p>Title: HES Professional</p> <p>Company Name: MPLX</p>		

Incident Report for 8/20/2022 Environmental Incident (ID: 1756)

Company Address: 2972 108 S Ave. SW, Dickinson, ND 58601	24 Hr.Phone: 24 Hr.Phone:	Company Address: 320 South View Drive, Suite 100, Bridgeport, WV 26330	24 Hr.Phone: 24 Hr.Phone:
Phone: 989-954-8227	Mobile/Pager: Mobile/Pager:	Phone: 304-841-5730	Mobile/Pager: Mobile/Pager:
Email:		Email:	

Incident Report for 8/20/2022 Environmental Incident (ID: 1756)

Incident and Risks

Expected Cause of Other: HDD Other: Unknown
Inadvertent Return :

Nature of Locale where Incident Occurred : Badlands Terrain

Weather : Clear/Sunny

Wind Direction : Wind Speed :

Distance from Nearest Occupied Building :

Number of Confirmed Injuries : 0

Distance from Nearest Water Well :

Number of Confirmed Fatalities : 0

Known Health Risks : N/A

Immediate Potential Threats (first 24 Hr) :

Delayed Potential Threats (after first 24 hr) :

None of the Above: Soil and vegetation

None of the Above: N/A

Response Details

Estimated Clean Up Completion Date : 08/26/2022

Waste Disposal Location :

Protective Actions Taken : IR's were contained with silt fence and hydro-vac truck sucked up Other Response Details :
surface fluids.

Evacuations :

No Response Reason :

Shelter In Place :

Clean Up Action Taken :

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
N/A	Bentonite	True Bore	No	No	3 gal	0.07	0	3 gal	0.07

Incident Observations

Note Added Date	Incident Observations
8/22/2022	Release of bentonite during boring activities. Follow up is required.